

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	554	((determin\$5 or detect\$5 or measur\$5 or inspect\$5 or monitor\$5 or calculat\$5) near8 stress) with (optic\$5 near2 (fiber or cable or waveguide or preform)) and @ad<=20021018	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:44
2	BRS	L2	210080	polariz\$5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:45
3	BRS	L3	368126	(rotat\$5 or turn\$5 or circulat\$5) near8 36812 (fiber or waveguide or device near2 under near2 test) or dut or cable or preform or source or laser or emitter or emitting)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 07:56
4	BRS	L4	554	((determin\$5 or detect\$5 or measur\$5 or inspect\$5 or monitor\$5 or calculat\$5) near8 stress) with (optic\$5 near2 (fiber or cable or waveguide or preform or device near2 under near2 test) or dut)) and @ad<=20021018	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 07:56
5	BRS	L5	105	1 and 2 and 3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 07:57
6	BRS	L6	347131	(rotat\$5 or turn\$5) near8 (fiber or waveguide or device near2 under near2 test) or dut or cable or preform or source or laser or emitter or emitting)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:17
7	BRS	L7	102	1 and 2 and 6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 08:02
8	BRS	L8	106269	phase near2 shift	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 08:02
9	BRS	L9	25	7 and 8	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 08:02
10	BRS	L10	32	((determin\$5 or detect\$5 or measur\$5 or inspect\$5 or monitor\$5 or calculat\$5) near8 (residual near2 stress) with (optic\$5 near2 (fiber or cable or waveguide or preform))) and @ad<=20021018	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:17
11	BRS	L11	2	8 and 10	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:17
12	BRS	L12	184482	(rotat\$5) near8 (fiber or waveguide or device near2 under near2 test) or dut or cable or preform or source or laser or emitter or emitting)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:19

	Type	L #	Hits	Search Text	DBs	Time Stamp
13	BRS	L13	18	10 and 12	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:44
14	BRS	L15	74897	polariz\$5 near3 (light or beam)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:45
15	BRS	L14	1	((determin\$5 or detect\$5 or measur\$5 or inspect\$5 or monitor\$5 or calculat\$5) near8 (circular near2 stress) ) with (optic\$5 near2 (fiber or cable or waveguide or preform)) and @ad<=20021018	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:45
16	BRS	L16	2	(circular near2 stress\$3) with (phase near2 shift\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:46
17	BRS	L17	1	1 and 16	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:46